

# F6 MultiTrack Field Recorder System Software Version History

You can always download the latest system software for free on the web site shown below.

<https://zoomcorp.com/>

---

## Version 1.90

- **Release to fix the following issues in July 2022**

1. When the recording setting mode was Float (32bit), entering and exiting the card reader in the USB menu would cause fader settings to change.
2. When checking 32-bit float WAV files in the F6 Control app Finder, the recording format would be shown incorrectly as "32kbps".

## Version 1.80

- **Released as the following bug fixes in April 2022**

1. Sound skips sometimes occur when recorded in Dual Mode.
2. There are cases in which a part of metadata is incorrect when recorded in Dual Mode.

## Version 1.70

- **Released as the following bug fixes in May 2021**

1. The internal timecode sometimes gains one frame when an external timecode is disconnected while the timecode is set to "Ext mode" or "Ext Auto Rec mode".
2. Improved low frequency characteristics of the filter used for internal processing.

## Version 1.60

- **Released as the following bug fix in October 2020**

1. F6 freezes when a user attempts to connect it to F6 Control App and Bluetooth timecode sync device simultaneously.

## Version 1.50

- **Released as the following bug fix in May 2020**

1. Noise is sometimes generated when F6 outputs low-level signal to LINE OUT.

## Version 1.40

- **Released as the following modification in March 2020**

1. Modification of firmware due to change of electronic parts.

## Version 1.30

- **Released as the bug fix in January 2020**

## Version 1.02

- **Released as mass production in September 2019**