
# L-12 Driver for Windows Software Version History



### Version 2.2.0

- Release to fix the following issue in March 2024
- 1. In Steinberg Cubase, "Recording error: Audio drop out detected." appears and recording stops.

#### Version 2.1.0

- Release to fix the following issue in June 2023
- 1. The following issues fixed when using Ableton Live or PreSonus Studio One on Windows computers that have CPUs with numerous threads/logical processors.
  - Audio input and output is sometimes not possible
  - DAW software sometimes freezes

## Version 2.0.2

- Released as following function update in September 2020
- 1. Added a function that enables the user to assign the signal through the master fader to audio channels 1&2 to send to PC.

Please refer to the L-12/L-20/L-20R audio driver version 2 supplementary manual.

#### Version 1.0.0

Released as mass production in August 2017