You can download the latest driver software for free on the web site below. https://zoomcorp.com/

Version 2.2.0

· Release to fix the following issue in March 2024

1. In Steinberg Cubase, "Recording error: Audio drop out detected." appears and recording stops.

Version 2.1.0

· Release to fix the following issue in June 2023

1. The following issues fixed when using Ableton Live or PreSonus Studio One on Windows computers that have CPUs with numerous threads/logical processors.

- Audio input and output is sometimes not possible
- DAW software sometimes freezes

Version 2.0.2

· Released as following function update in September 2020

1. Added a function that enables the user to assign the signal through the master fader to audio channels 1&2 to send to PC.

Please refer to the L-12/L-20/L-20R audio driver version 2 supplementary manual.

Version 1.0.0

· Released as mass production in August 2018